

saheco

**SINCRO
SV-A125**

Poligono Industrial Foradada - 08580 - Sant Quirze de Besora (Barcelona)

Telf. 34-93.852.92.23, Fax.34-93.852.91.59

Export. Telf. 34-93.852.96.15, Fax.34-93.852.91.76


e-mail: saheco@saheco.com

web: www.saheco.com



**GRUPO
TORREMAT**












038060623




$$A=H-101.5$$

10115						
(a)			4	(e)		1
(b)			4	(f)		1
(c)			2	(g)		2
(d)			1	(h)		3
(w)			1	(i)		1
				(j)		2







 M6X10
 M6X18




 M6X16
 M6X22




Posicion Pinzas en las Hojas
 Clamps Situation on sheets
 Situation pinces dans les portes




11




12




13



14



15



16

17


The belt must be strained before fix the screws.

f1

f2


D

17  The belt must be strained before fix the screws.



D

17  The belt must be strained before fix the screws.



D

19

Diagram 19 illustrates the side profile of the cabinet. It shows the top panel, side panel, and bottom panel. A curved arrow indicates the top panel is hinged. A dashed line shows the internal structure. A small inset shows a detail of the bottom panel's attachment to the side panel using screws.